



















APPENDIX I


















MANSION ARTIFACTS



















Interior/ Exterior	OM Map	Survey	Description		Location	Qty	Notes
E	D-E	C1	Wrought Iron ceiling lantern- 5 vellum		Courtyard	2	Removed- In Storage
E		C2	Fireplace		Courtyard	1	North Wall
E		C3	Hand Carved Wood Truss		Courtyard	4	North End
E		C4	Hand Carved Wood Post		Courtyard		Throughout Courtyard
E	A-C	C5	Wrought Iron ceiling lantern with Vellum		Courtyard	3	Removed- In Storage
E	F-H	C5	Wrought Iron ceiling lantern with Vellum		Courtyard	3	Removed- In Storage
E		C6	Della Robbia		Courtyard	1	Removed- In Storage
E		C7	Della Robbia		Courtyard	1	Removed- In Storage
E		C8	Della Robbia		Courtyard	1	Removed- In Storage
E		C9	Vents		Courtyard	2	South Wall
E		C10	Hand Carved Wood Screens		Courtyard	3	Triple window-South Wall
E		C11	Braided chain link fence		Courtyard		Surrounding the fountain
E		C12	American Perforator		Courtyard	1	Against South Wall
E		C13	Della Robbia		Courtyard	1	Removed- In Storage
E		C14	Della Robbia		Courtyard	1	Removed- In Storage
E		C15	Della Robbia		Courtyard	1	Removed- In Storage
E		C16	Fountain		Courtyard	1	

E	A-G	C17	Wood Paneled Door		Courtyard	7	Removed- In Storage
E		C18	Small Wood Casement Window		Courtyard		
E	A-H	E1	Wall Lantern		Gate Entry	6	Removed- In Storage
E		E2	Wrought Iron Gates		Gate Entry	2	East & South Wall
E		E3	Copper Lights		Gate Entry	14	Along walkway
E		E4	Della Robbia		Front Breezeway	1	Removed- In Storage
E	A	E5	Wrought Iron ceiling light fixture		Front Breezeway	1	Removed- In Storage
E		E6	Missing Plaque		Front Breezeway	1	Missing
E		E7	Della Robbia		Front Breezeway	1	Removed- In Storage
E	A-B	E8	Wrought Iron wall lantern		Main Entry	1	Removed- In Storage
E		E9	Della Robbia		Front Breezeway	1	Removed- In Storage
E		E10	Missing Plaque		Front Breezeway	1	Missing
E	B	E11	Wrought Iron ceiling light fixture		Front Breezeway	1	Removed- In Storage
E		E12	Front Door		Main Entry	1	Wood and Metal door
E		E13	Wood Slats		West Wall Outside	1	Slats block window
E		E14	Large Avocado Tree		West Wall Outside	1	Adjacent to Triple door
E		E15	Plant pot holders		West Wall Outside	5	
E	A-B	E16	Bell Curved Light		Main Entry	2	Removed- In Storage

E	E17	Triple hung wood windows		West Wall Outside	1	Small awning window	
E	E18	Wood casement window		West Wall Outside		Next to cooler- missing shutters	
E	E19	Housing for electrical Panel		West Wall Outside		Near office	
E	E20	Wrought iron wall light fixture		West Wall Outside		Centered above the west wall	
E	E21	Wrought iron- braided-"s" shaped hook for shut					
E	E22	Avairy		North-West corner			
E	E23	Well		North Portion			
E	E24	Wrought iron braided post & chain					
I	A1	Fountain		Service Area	1		
I	A-D	A2	Wrought Iron sconce with 2 lights		Service Area	4	Removed- In Storage
I	A-B	B1	Hand Carved door		Dining	2	Removed- In Storage
I		B2	Della Robbia		Dining	1	Removed- In Storage
I	A-F	B3	Wrought Iron Wall Sconce w/ 5 lights		Dining	6	Removed- In Storage
I		B4	Inset Wall Plaque- Lion Décor		Dining	1	Removed- In Storage
I		B5	Pocket door		Reception-Lobby	2	East & West Ends
I		B6	Oil on canvas		Reception-Lobby		Above West Pocket door - removed and on loan to the History Museum of Art, Ontario, CA
I		B7	Wood french doors w/ shutter		Dining	1	West wall of dining room

I		C1	Wood 8 Paneeled door		Office	1	Door to New office
I		C2	Inset wall Shelves		Office	2	South wall
I	A-D	C3	Wrought Iron sconce with lamp shade		Office	4	Removed- In Storage
I	E	C4	Chandelier		Office	1	Removed- In Storage
I		C5	Mother of Pearl / Brass doorbell		Office	1	East Wall
I		C6	Wood Casement windows w/ wood shutters		Office	3	North Wall
I		C7	Diamond patterned Floor		Office		Hallway to New office
I		C8	Marble herringbone tile		Office		Bathroom in New office
I	A-D	D1	Wood Paneled Door- Diamond Pattern		Reception-Lobby	4	Removed- In Storage
I		D2	Push button light switches		Reception-Lobby	1	
I	A-B	E1	Wrought Iron Wall Sconce w/ 5 lights		Reception-Lobby	2	Removed- In Storage
I		E2	Fireplace With wrought Iron screen		Reception-Lobby	1	Along North wall
I	(2) Alcove	E3	Wall niche w/ Wood Shutters		Reception-Lobby	2	Removed- In Storage
I		E4	Oil on Canvas		Reception-Lobby	1	Above East Pocket door - removed and on loan with History Museum of Art, Ontario, CA
I	A-L	E5	Wood Shutters		Dining	12	Removed- In Storage
I	A-R	E5	Wood Shutters		Reception-Lobby	18	Removed- In Storage
I		E6	Oil on canvas		Reception-Lobby	1	Above East Pocket door - removed and on loan with History Museum of Art, Ontario, CA

I		F1	Oil on canvas		Library	1	Above West Pocket door - removed and on loan with History Museum of Art, Ontario, CA
I	A-E	F2	Wrought Iron Wall Sconce w/ 6 lights		Library	5	Removed- In Storage
I		F3	Stained glass wood window with lion Crest		Library	1	Center of East Wall
I		F4	Wood inset book shelves		Library	4	1 north, 1 south, 2 west
I		F5	Wood casement windows in arched inset		Library	3	Along East wall
I		F6	Fireplace with plaster surrounds		Library	1	North Wall
I		F7	Passage door		Library	1	North wall
I		F8	Push button switch		Library	1	West Wall
I		F9	Push button electrical panel		Library	1	Hallway outside Library
I		G1	Painted wood paneled door		Bridal/ Master bedroom	1	Door leading from hallway to room
I		G2	Ceiling light fixture with brass leaves		Bridal/ Master bedroom	1	Entry way
I		G3	Wall Wood Casement Window w/ flower des		Bridal/ Master bedroom	3	West wall
I		G4	Triple wood casement		Bridal/ Master bedroom	1	Along east wall
I		G5	Celing light fixture with leaf design		Bridal/ Master bedroom	1	Bathroom of Master bedroom
I		G6	Closet		Bridal/ Master bedroom		
I		G7	Vanity		Bridal/ Master bedroom		
I		H1	Wood paneled door		Bridal/ Master bedroom	1	leads to courtyard

I	H2	pedestal bathroom sinck with spout		Bridal/ Master bedroom	1	
I	H3	Bath tub		Bridal/ Master bedroom	2	
I	J1	Framed Mirror			1	
I	J2	White subway tile shower				
I	J3	Hand carved wood door			1	Lounge off of hallway

